

August 12, 2011



U.S. Department
of Transportation

East Building, PHH-30
1200 New Jersey Avenue S.E.
Washington, D.C. 20590

**Pipeline and Hazardous
Materials Safety Administration**

DOT-SP 14854
(SECOND REVISION)

EXPIRATION DATE: July 31, 2015

(FOR RENEWAL, SEE 49 CFR § 107.109)

1. GRANTEE: Airgas East
Bellmawr, NJ
2. PURPOSE AND LIMITATION:
 - a. This special permit authorizes the transportation in commerce of certain hazardous materials in DOT Specification 3AL cylinders manufactured from aluminum alloy 6061-T6 that are requalified every ten years rather than every five years using 100% ultrasonic examination. This special permit provides no relief from the Hazardous Materials Regulations (HMR) other than as specifically stated herein. The most recent revision supersedes all previous revisions.
 - b. The safety analyses performed in the development of this special permit only considered the hazards and risks associated with the transportation in commerce.
 - c. No party status will be granted to this special permit.
3. REGULATORY SYSTEM AFFECTED: 49 CFR Parts 106, 107 and 171-180.
4. REGULATIONS FROM WHICH EXEMPTED: 49 CFR § 180.209(a) and part of § 180.209(b), in that DOT 3AL cylinders may be requalified every ten years and are not required to be hammer tested prior to each refill; and § 180.209(b)(1)(iv) in that ultrasonic examination is authorized in lieu of hydrostatic testing and visual inspection.
5. BASIS: This special permit is based on the application of Airgas East dated July 22, 2011, submitted in accordance with § 107.109.

6. HAZARDOUS MATERIALS (49 CFR § 172.101):

Hazardous Materials Description			
Proper Shipping Name	Hazard Class/ Division	Identification Number	Packing Group
Non-corrosive liquefied or non-liquefied compressed gases, or mixtures of such compressed gases, classed as Division 2.1, (flammable gas) and Division 2.2, (nonflammable gas) which are authorized in the HMR for transportation in DOT 3AL cylinders.	2.1, 2.2	Various	N/A

7. SAFETY CONTROL MEASURES:

a. PACKAGING: - Packaging prescribed is a DOT-3AL specification cylinder made of aluminum alloy 6061-T6 that is subjected to the periodic retesting, re-inspection and marking prescribed in §§ 180.205, 180.209 and 180.213 except that:

- (1) The cylinder is not required to be hammer tested prior to each refill;
- (2) Each cylinder must be retested at least once every 10 years by utilizing the 100 percent ultrasonic examination (UE) of sidewall as described in DOT-SP 14313 (Air Gas) except that for all cylinders the flat bottom hole (FBH) used as referenced standard (calibration) must have diameter and depth less than or equal to 1/8" and 0.025" respectively;
- (3) Each cylinder passing retests under the provisions of this special permit must be marked in accordance with DOT-SP 14313. Additionally each cylinder must be plainly marked "DOT-SP 14854" followed by "*" as specified in § 180.209(b) (1) (VI). Cylinders whose outside diameter is less than 5.0" may be marked using a

August 12, 2011

1/8" high character or alternatively, a label bearing "DOT-SP 14854" followed by "*" may be affixed to the cylinder's side wall near the shoulder region. Marking and/or labeling must be permanent and durable through each requalification period.

b. OPERATIONAL CONTROLS:

- (1) Cylinders under this special permit must be remain in dedicated service;
- (2) Prior to each filling - the company filling the cylinder must ensure:
 - (i) Gas mixtures are chemically compatible with cylinder material (aluminum alloy) and do not have an adverse effect on the cylinder's strength.
 - (ii) Quality of the gas and gas mixture meet all requirements of §180.209(b) (ii) and have dew point below minus 52 °F at 1 atmosphere;
- (3) Prior to each fill the cylinder under this special permit must be externally inspected in accordance with CGA pamphlet C6.1;
- (4) Any cylinder exhibiting evidence of fire or excessive heat damage may not be retested under the terms of this special permit.

8. SPECIAL PROVISIONS:

a. A person who is not a holder of this special permit who receives a package covered by this special permit may reoffer it for transportation provided no modification or change is made to the package and it is reoffered for transportation in conformance with this special permit and the HMR.

b. A current copy of this special permit must be maintained at each facility where the package is offered or reoffered for transportation.

August 12, 2011

- c. The ultrasonic examination data, results, and additional technical information deemed pertinent in successful application of the UE shall be reported to OHMSPA. The purpose of this information is to determine whether certain examination procedures and criteria require modification. For any rejected cylinder, the defect causing the rejection must be fully characterized and profiled. That is, the specific type of defect should be identified (i.e. isolated pits, line corrosion or SBT crack) and the specific size of the defect should be determined (i.e. length, depth, width, diameter, area, etc.). The cylinder type, size, minimum design wall thickness, age, etc. of the rejected cylinder must be reported. The ultrasonic signal profile should be reported for any defect causing the cylinder to be rejected. These results must be summarized and reported to OHMSPA on an annual basis. The special permit holder must submit to OHMSPA an evaluation of the effectiveness of the ultrasonic examination program authorized by this special permit as part of any request to renew the special permit submitted in accordance with § 107.109.
- d. The total number of cylinders tested and rejected under this special permit must be reported to OHMSPA by cylinder class and age. These results must be summarized and reported on an annual basis.
- e. Transportation of Division 2.1 (flammable gases) is not authorized aboard cargo vessel or aircraft unless specifically authorized in the Hazardous Materials Table (§ 172.101).
- f. Transportation of oxygen is only authorized by aircraft when in accordance with § 175.501.
9. MODES OF TRANSPORTATION AUTHORIZED: Motor vehicle, rail freight, cargo vessel, cargo aircraft only and passenger carrying aircraft, as currently authorized by the HMR for the hazardous materials being transported.
10. MODAL REQUIREMENTS: A current copy of this special permit must be carried aboard each cargo vessel, aircraft, or motor vehicle used to transport packages covered by this special permit. The shipper must furnish a copy of this special permit to the air carrier before or at the time the shipment is tendered.

August 12, 2011

11. COMPLIANCE: Failure by a person to comply with any of the following may result in suspension or revocation of this special permit and penalties prescribed by the Federal hazardous materials transportation law, 49 U.S.C. 5101 et seq:
- o All terms and conditions prescribed in this special permit and the Hazardous Materials Regulations, 49 CFR Parts 171-180.
 - o Persons operating under the terms of this special permit must comply with the security plan requirement in Subpart I of Part 172 of the HMR, when applicable.
 - o Registration required by § 107.601 et seq., when applicable.

Each "Hazmat employee", as defined in § 171.8, who performs a function subject to this special permit must receive training on the requirements and conditions of this special permit in addition to the training required by §§ 172.700 through 172.704.

No person may use or apply this special permit, including display of its number, when this special permit has expired or is otherwise no longer in effect.

Under Title VII of the Safe, Accountable, Flexible, Efficient Transportation Equity Act: A Legacy for Users (SAFETEA-LU)—"The Hazardous Materials Safety and Security Reauthorization Act of 2005" (Pub. L. 109-59), 119 Stat. 1144 (August 10, 2005), amended the Federal hazardous materials transportation law by changing the term "exemption" to "special permit" and authorizes a special permit to be granted up to two years for new special permits and up to four years for renewals.

12. REPORTING REQUIREMENTS: Shipments or operations conducted under this special permit are subject to the Hazardous Materials Incident Reporting requirements specified in 49 CFR §§ 171.15 Immediate notice of certain hazardous materials incidents, and 171.16 Detailed hazardous

August 12, 2011

materials incident reports. In addition, the grantee(s) of this special permit must notify the Associate Administrator for Hazardous Materials Safety, in writing, of any incident involving a package, shipment or operation conducted under terms of this special permit.

Issued in Washington, D.C.:



for Dr. Magdy El-Sibaie

Associate Administrator for Hazardous Materials Safety

Address all inquiries to: Associate Administrator for Hazardous Materials Safety, Pipeline and Hazardous Material Safety Administration, U.S. Department of Transportation, East Building PHH-30, 1200 New Jersey Avenue, Southeast, Washington, D.C. 20590.

Copies of this special permit may be obtained by accessing the Hazardous Materials Safety Homepage at http://hazmat.dot.gov/sp_app/special_permits/spec_perm_index.htm. Photo reproductions and legible reductions of this special permit are permitted. Any alteration of this special permit is prohibited.

PO: Toughiry/SEG

August 12, 2011**Attachment 1**

Only the following locations have been authorized by OHMSPA to perform requalification functions described in this special permit. Each authorization is valid only when the associated RIN approval and this special permit remain current. As acknowledged by the list of names and locations below, the grantee of this special permit must notify OHMSPA of any change in approval status, company name, address, or new test facility additions within 20 days of that change.

Airgas East

A473 Airgas East
2900 52nd Avenue
Hyattsville, MD 20781

H119 Airgas East
270 Benigno Blvd.
Bellmawr, NJ 08031

H684 Airgas East
84 Karner Road
Albany, NY 12205

H841 Airgas East
90 Research Rd
Hingham, MA 02043

Airgas Great Lakes

H369 Airgas Great Lakes
5018 Empire Way
Lansing, MI 48917

H728 Airgas Great Lakes
7600 Oakleaf Road
Oakwood Village, OH 44146

H609 Airgas Great Lakes
38098 Van Born Road
Wayne, MI 48184

H702 Airgas Great Lakes
1200 Gest Street, Suite B
Cincinnati, OH 45203

H696 Airgas Great Lakes
160 Glendale Milford Rd.
Miamiville, OH 45147

Airgas Intermountain

H725 Airgas Intermountain
8775 East 93rd Place
Henderson, CO 80640

H131 Airgas Intermountain
604 W. 3rd Street
Pueblo, CO 81003

H467 Airgas Intermountain
3415 South 700 West
Salt Lake City, UT 84119-4140

Airgas Mid-America

H211 Airgas Mid America
9221 Wheeler Arch Rd
Mountain Grove, MO 65711

A718 Airgas Mid America
440 West Industry Drive
Kingsport, TN 37660

Airgas Mid-South

D054 Airgas Mid South
1231 N. Harrison
Shawnee, OK 74801

Airgas Northern California-Nevada

C935 Airgas NCN
6801 Florin Perkins Road
Sacramento, CA 95828

August 12, 2011**Airgas NorPac**

H142 Airgas NorPac
1165 Columbia Blvd
Longview, WA 98632

H474 Airgas NorPac
2043 South 35th St.
Tacoma, WA 98409

Airgas North Central

H682 Airgas North Central
401 Sentry Drive
Waukesha, WI 53186

H545 Airgas North Central
5235 South 9th Avenue
La Grange, IL 60525

D057 Airgas North Central
410 S.E. Creekview Drive
Ankeny, IA 50021

Airgas National Welders

B328 Airgas National Welders
109 Hinnant Rd.
Goldsboro, NC 27530

H486 Airgas National Welders
1870 Wren Turnpike
Gastonia, NC 28052

Airgas South

H118 Airgas South
1311 Fulton Ind. Blvd,
Building C
Atlanta, GA 30336

H268 Airgas South
9416 Broadway Avenue
Tampa, FL 33619

H367 Airgas South
3648 Oakcliff Road
Atlanta, GA 30340

H992 Airgas South
5225 Phillips Highway,
Suite #1
Jacksonville, FL 32207

Airgas Southwest

H437 Airgas Southwest
2615 Joe Field Road
Dallas, TX 75229

H693 Airgas Southwest
2501 S. Pearl
Belton, TX 76513

H525 Airgas Southwest
35114 Hwy 30
Geismar, La. 70734

H996 Airgas Southwest
3502 Pan American Freeway
Albuquerque, NM 87107

Airgas West

A132 Airgas West
11711 South Alameda Street
Los Angeles, CA

G987 Airgas West
191 Kettering Drive
Ontario, CA 91761